



www.micro-blaze.com
800-626-6598
713-691-6468

Micro-Blaze Out® Plus

Chevron Fire Foam Test Held Spring 2001

3% Premix – Type III – 93 Octane Gas – 0.06 gpm / sq ft Application Rate

Test #	Concentrate	Control [min:sec]	Extinguishment [min : sec]	First Torch*	Second Torch**	10 sq ft Burnback Test	
						Area [sq ft]	Notes
16	Verde Environmental, Inc.: Micro-Blaze Out Plus® 3% AFFF Lot # 010119	1:43	2:33	NO IGNITION	NO IGNITION	Self-Extinguishment	Walkover 14:00 – 14:55. Self-extinguishment at 14:55.
15	National Foam : Univ Gold 1 x 3 AR-AFFF Lot # 1004 1/01/WC	1:50	2:30	NO IGNITION	NO IGNITION	Self-Extinguishment	Walkover 14:00 – 15:45. Self-extinguishment at 15:45.
10	Ansul: Ansulite 3 x 3 Lot # LV 8014	2:03	2:44	NO IGNITION	NO IGNITION	Self-Extinguishment	Walkover 14:00 – 15:06. Self-extinguishment at 15:06.
12	Buckeye Foam: Buckeye 3%-3% AR-AFFF (BFC-33) Lot # 70003	1:52	2:46	NO IGNITION	NO IGNITION	Self-Extinguishment	Walkover 14:00 – 15:42. Self-extinguishment at 15:42.

Notes:

*: First torch was conducted between 4:30 and 5:30 for all tests.

** : Second torch was conducted between 11:00 and 11:50 for all tests.

The following manufacturers / products FAILED the above testing:

- Chemguard / 1% - 3% AR-AFFF
- Akron / Style 950 Pyrocool FEF
- Williams F&HC / Thunderstorm ATC F – 601/ATC Plus F
- Angus / Tridol ATF 3 x 3