



Certified Utility Operators
(Water and Wastewater)

Dwight Vavra
Mobile: (979)-241-8392
Home: (979)-843-5010

PO Box 413
Markham, TX 77456
dgvavra@hotmail.com

November 10, 2006

RE: CATFISH CLEANING PLANT

The catfish cleaning plant had a strong odor and the drain lines were filled with fat and grease. The grease trap had approximately 12 inches of grease on top of the water.

A 2% solution of Micro-Blaze Fog was applied to the grounds and overflow areas around the grease trap. The strong odor was gone in 48 hours.

Micro-Blaze Fog was added to the drains in the plant. After 48 hours, the drain lines were flowing freely and the 12 inches of grease in the grease trap was reduced to 2 inches.

There was also a heavy buildup of grease and fat around the point of discharge into the wastewater plant. This buildup disappeared in approximately 10 days.

Respectfully,

Dwight Vavra, CUO
Certified Utility Operators